


Preparing the Tools

- The firmware update requires the following equipment:
 - Multiloader v3.14 or upper
 - Multiloader package
 - Ethernet connection cable
 - VW3A8222 specific cable




Multiloader kit – VW3A8121



Specific cable– VW3A8122

Connection ATV320...B

- Connect a standard Ethernet cable from the Multiloader to the drive [1]
- Connect the specific cable from the Multiloader to the drive [2]



Connection ATV320...C

- Connect a standard Ethernet cable from the Multiloader to the drive [1]
- Connect the specific cable from the Multiloader to the drive [2]

