

in a configuration where the drive is connected and supplied by another drive via the DC bus, we have to set DCBS parameter (**Generic Functions/DC-Bus Ref Link**) to **"Drive with REC"** as showed in the picture in attachment. This setting avoid to get "Precharge Capacitor" faults.

