

What is the important precondition that should be taken into account before testing Logic discrimination in recent firmware versions of Sepam 40, 60 and 80?

According to some firmware evolution the circuit breaker closed position is now added as a precondition to Logic discrimination algorithm. It means that Logic discrimination is in service if circuit breaker position is closed. In other words, with a circuit breaker in open position, even though the relay is receiving blocking signal from downstream, its logic discrimination feature will not work.

This new condition done on Sepam series 40, 60 and 80 has to be taken into account when doing tests during commissioning.

In this table you will see the first firmware version and date which included this evolution:

Sepam Series	Firmware Version	Date
40	V8.04	March-2013
60	V8.02	May-2013
80	V8.02	May-2013

AEDL3