


R9XPN115N

R9XPN115



PLEASE NOTE

- This equipment must be installed and maintained by a qualified electrician in accordance with the appropriate statutory regulations and codes of practice.
- All applicable local, regional and national regulations must be complied with during the installation, use, maintenance and replacement of this device.
- This product should not be installed if, when unpacking it, you observe that it is damaged.
- Schneider Electric cannot be held responsible in the event of noncompliance with the instructions in this document and in the documents to which it refers.
- The service instruction must be observed throughout the life time of this product.

⚡ ⚠ DANGER

HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH



- Turn off all power supplying this product before working on it.
- Use a voltage tester with a suitable rated voltage in order to check that all active conductors aren't energized.
- Carefully inspect the work area to check that no tools or objects could have been left inside the equipment.

Failure to follow these instructions will result in death or serious injury.

1 Unboxing

R9XPN115N

R9XPN115



Commercial Reference Number	Comb Busbar (Number of Ways)	(A)	(B)	(C)	(D)	(E)
		Connector	Tooth Cap	Neutral Block	End Cap (Spare)	Instruction Sheet
R9XPN115N	1 (15 Way)	3	6	1	2	1
R9XPN115	1 (15 Way)	2	4	-	2	1

2 Top Feed Busbar Installation

DANGER


HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

- Check that the busbar is fully inserted inside all the protective devices.
 - Tighten all connections to recommended torque settings.
- Failure to follow these instructions will result in death or serious injury.

Single Phase

One row


R9XPN115N



Note: For torque value refer to the respective device instruction sheet.

Multi row

R9XPN115N



Cutting, End Cap and Tooth Cap Installation

R9XPN115, R9XPN115N

