



Your controller hardware evolved, please read this before downgrading the firmware

Modicon M258 / LMC058 Hardware - Firmware compatibility

The hardware version changed due to component obsolescence, so a new firmware is now available and mandatory for all product hardware versions equal to or greater than PV:16.

For SoMachine V3.x : M258_LMC058_Firmware_v2.0.31.40

https://www.schneider-electric.com/en/download/document/M258_LMC058_Firmwar_v2.0.31.40/

V2.0.31.40



Quick link to firmware with QR Code:

For SoMachine V4.x : M258_LMC058_Firmware_v4.0.3.6

https://www.schneider-electric.com/en/download/document/M258_LMC058_Firmware_v4.0.3.6/

V4.0.3.6



Quick link to firmware with QR Code:

The new hardware (PV ≥ 16) needs this firmware to function correctly.
All products with PV ≥ 16 are manufactured with firmware V4.0.3.6.

Compatibility table

Software Version	Firmware Version		Product Hardware Version (PV)			
			From 2 to 6	From 6a to 8	From 9 to 15	From 16
SoMachine V3.x	Through	V2.0.21.15	✓	✓	✗	✗
	From To	V2.0.31.21 V2.0.31.39	✓	✓	✓	✗
	From	V2.0.31.40	✗	✓	✓	✓
SoMachine V4.x	From To	V4.0.2.6 V4.0.3.2	✓	✓	✓	✗
	From	V4.0.3.6	✗	✓	✓	✓