

# Tesys to Everlink cross references

| Old Tesys Reference | Everlink Equivalent      |
|---------------------|--------------------------|
| LRD3359A66          | Supeseded by LRD3656     |
| LRD3359             | Supeseded by LRD365      |
| LRD3357A66          | Supeseded by LRD3506     |
| LRD3357             | Supeseded by LRD350      |
| LRD3355A66          | Supeseded by LRD3406     |
| LRD3355             | Supeseded by LRD340      |
| LRD3353A66          | Supeseded by LRD3326     |
| LRD3353             | Supeseded by LRD332      |
| LRD3322A66          | Supeseded by LRD3256     |
| LRD3322             | Supeseded by LRD325      |
| LRD3321A66          | Supeseded by LRD3186     |
| LRD3321             | Supeseded by LRD318      |
| LRD3316A66          | Supeseded by LRD3136     |
| LRD3316             | Supeseded by LRD313      |
| LR3D3359            | Supeseded by LR3D365     |
| LR3D3357            | Supeseded by LR3D350     |
| LR3D3355            | Supeseded by LR3D340     |
| LR3D3353            | Supeseded by LR3D332     |
| LR3D3322            | Supeseded by LR3D325     |
| LR2D3359S340        | Supeseded by LRD365      |
| LR2D3359S054        | Supeseded by LRD365      |
| LR2D3359A66         | Supeseded by LRD3656     |
| LR2D3359            | Supeseded by LRD365      |
| LR2D3357S340        | Supeseded by LRD350      |
| LR2D3357S054        | Supeseded by LRD350      |
| LR2D3357A66         | Supeseded by LRD3506     |
| LR2D3357            | Supeseded by LRD350      |
| LR2D3355S340        | Supeseded by LRD340      |
| LR2D3355S054        | Supeseded by LRD340      |
| LR2D3355A66         | Supeseded by LRD3406     |
| LR2D3355            | Supeseded by LRD340      |
| LR2D3353S340        | Supeseded by LRD332      |
| LR2D3353S103        | Supeseded by LRD332      |
| LR2D3353S054        | Supeseded by LRD332      |
| LR2D3353A66         | Supeseded by LRD3326     |
| LR2D3353            | Supeseded by LRD332      |
| LP1D65004UD         | superseded by LC1DT80AUD |
| LP1D65004SW         | superseded by LC1DT80ASD |
| LP1D65004SD         | superseded by LC1DT80ASD |
| LP1D65004RD         | superseded by LC1DT80ARD |
| LP1D65004ND         | superseded by LC1DT80AND |
| LP1D65004MW         | superseded by LC1DT80AMD |
| LP1D65004MD         | superseded by LC1DT80AMD |
| LP1D65004JW         | superseded by LC1DT80AJD |
| LP1D65004JD         | superseded by LC1DT80AJD |
| LP1D65004GD         | superseded by LC1DT80AGD |
| LP1D65004FW         | superseded by LC1DT80AFD |
| LP1D65004FD         | superseded by LC1DT80AFD |

|              |                                                                        |
|--------------|------------------------------------------------------------------------|
| LP1D65004EW  | superseded by LC1DT80AED                                               |
| LP1D65004ED  | superseded by LC1DT80AED                                               |
| LP1D65004CW  | superseded by LC1DT80ACD                                               |
| LP1D65004CD  | superseded by LC1DT80ACD                                               |
| LP1D65004BW  | superseded by LC1DT80ABD                                               |
| LP1D65004BD  | superseded by LC1DT80ABD                                               |
| LP1D650046SW | superseded by LC1DT80A6SD                                              |
| LP1D40004UD  | superseded by LC1DT60AUD                                               |
| LP1D40004SW  | superseded by LC1DT60ASD                                               |
| LP1D40004SD  | superseded by LC1DT60ASD                                               |
| LP1D40004RD  | superseded by LC1DT60ARD                                               |
| LP1D40004ND  | superseded by LC1DT60AND                                               |
| LP1D40004MW  | superseded by LC1DT60AMD                                               |
| LP1D40004MD  | superseded by LC1DT60AMD                                               |
| LP1D40004JW  | superseded by LC1DT60AJD                                               |
| LP1D40004JD  | superseded by LC1DT60AJD                                               |
| LP1D40004GD  | superseded by LC1DT60AGD                                               |
| LP1D40004FW  | superseded by LC1DT60AFD                                               |
| LP1D40004FD  | superseded by LC1DT60AFD                                               |
| LP1D40004EW  | superseded by LC1DT60AED                                               |
| LP1D40004ED  | superseded by LC1DT60AED                                               |
| LP1D40004CW  | superseded by LC1DT60ACD                                               |
| LP1D40004CD  | superseded by LC1DT60ACD                                               |
| LP1D40004BW  | superseded by LC1DT60ABD                                               |
| LP1D40004BD  | superseded by LC1DT60ABD                                               |
| LP1D400046UD | superseded by LC1DT60A6UD                                              |
| LP1D400046SW | superseded by LC1DT60A6BD                                              |
| LP1D400046MW | superseded by LC1DT60A6MD                                              |
| LP1D400046FW | superseded by LC1DT60A6FD                                              |
| LP1D400046FD | superseded by LC1DT60A6FD                                              |
| LP1D400046BW | superseded by LC1DT60A6BD                                              |
| LP1D400046BD | superseded by LC1DT60A6BD                                              |
| LC3D50V7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50V7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50V5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50U7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50U7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50U5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50T7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50T6     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50S5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50R7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50R7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50R5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50Q7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50Q7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50Q5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50P7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50P7     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50P5     | Superseded by Everlink offer - please talk to our technical department |
| LC3D50N7A64  | Superseded by Everlink offer - please talk to our technical department |
| LC3D50N7     | Superseded by Everlink offer - please talk to our technical department |

[illegible]

|             |                                                                        |
|-------------|------------------------------------------------------------------------|
| LC3D40B7A64 | Superseded by Everlink offer - please talk to our technical department |
| LC3D40B7    | Superseded by Everlink offer - please talk to our technical department |
| LC3D40B5    | Superseded by Everlink offer - please talk to our technical department |
| LC2D65W6    | superseded by LC2D65AW7                                                |
| LC2D65V7    | superseded by LC2D65AV7                                                |
| LC2D65V5    | superseded by LC2D65AV7                                                |
| LC2D65U7    | superseded by LC2D65AU7                                                |
| LC2D65U6    | superseded by LC2D65AU7                                                |
| LC2D65U5    | superseded by LC2D65AU7                                                |
| LC2D65T6    | superseded by LC2D65AT7                                                |
| LC2D65S5    | superseded by LC2D65AS7                                                |
| LC2D65R7    | superseded by LC2D65AR7                                                |
| LC2D65R6    | superseded by LC2D65AR7                                                |
| LC2D65R5    | superseded by LC2D65AR7                                                |
| LC2D65Q7    | superseded by LC2D65AQ7                                                |
| LC2D65Q6    | superseded by LC2D65AQ7                                                |
| LC2D65Q5    | superseded by LC2D65AQ7                                                |
| LC2D65P7    | superseded by LC2D65AP7                                                |
| LC2D65P5    | superseded by LC2D65AP7                                                |
| LC2D65N7    | superseded by LC2D65AN7                                                |
| LC2D65N6    | superseded by LC2D65AN7                                                |
| LC2D65N5    | superseded by LC2D65AN7                                                |
| LC2D65M7    | superseded by LC2D65AM7                                                |
| LC2D65M6    | superseded by LC2D65AM7                                                |
| LC2D65M5    | superseded by LC2D65AM7                                                |
| LC2D65LE7   | superseded by LC2D65ALE7                                               |
| LC2D65L7    | superseded by LC2D65AL7                                                |
| LC2D65K7    | superseded by LC2D65AK7                                                |
| LC2D65J5    | superseded by LC2D65AJ5                                                |
| LC2D65G7    | superseded by LC2D65AG7                                                |
| LC2D65G6    | superseded by LC2D65AG7                                                |
| LC2D65G5    | superseded by LC2D65AG7                                                |
| LC2D65FE7   | superseded by LC2D65AFE7                                               |
| LC2D65FE5   | superseded by LC2D65AFE7                                               |
| LC2D65F7    | superseded by LC2D65AF7                                                |
| LC2D65F6    | superseded by LC2D65AF7                                                |
| LC2D65F5    | superseded by LC2D65AF7                                                |
| LC2D65E7    | superseded by LC2D65AE7                                                |
| LC2D65E6    | superseded by LC2D65AE7                                                |
| LC2D65E5    | superseded by LC2D65AE7                                                |
| LC2D65D7    | superseded by LC2D65AD7                                                |
| LC2D65B7    | superseded by LC2D65AB7                                                |
| LC2D65B6    | superseded by LC2D65AB7                                                |
| LC2D65B5    | superseded by LC2D65AB7                                                |
| LC2D50W6    | superseded by LC2D50AW7                                                |
| LC2D50V7    | superseded by LC2D50AV7                                                |
| LC2D50V5    | superseded by LC2D50AV7                                                |
| LC2D50U7    | superseded by LC2D50AU7                                                |
| LC2D50U6    | superseded by LC2D50AU7                                                |
| LC2D50U5    | superseded by LC2D50AU7                                                |
| LC2D50T6    | superseded by LC2D50AT7                                                |
| LC2D50R7    | superseded by LC2D50AR7                                                |

|           |                          |
|-----------|--------------------------|
| LC2D50R6  | superseded by LC2D50AR7  |
| LC2D50R5  | superseded by LC2D50AR7  |
| LC2D50Q7  | superseded by LC2D50AQ7  |
| LC2D50Q6  | superseded by LC2D50AQ7  |
| LC2D50Q5  | superseded by LC2D50AQ7  |
| LC2D50P7  | superseded by LC2D50AP7  |
| LC2D50P5  | superseded by LC2D50AP7  |
| LC2D50N7  | superseded by LC2D50AN7  |
| LC2D50N6  | superseded by LC2D50AN7  |
| LC2D50N5  | superseded by LC2D50AN7  |
| LC2D50M7  | superseded by LC2D50AM7  |
| LC2D50M6  | superseded by LC2D50AM7  |
| LC2D50M5  | superseded by LC2D50AM7  |
| LC2D50L7  | superseded by LC2D50AL7  |
| LC2D50K7  | superseded by LC2D50AK7  |
| LC2D50J5  | superseded by LC2D50AJ5  |
| LC2D50G7  | superseded by LC2D50AG7  |
| LC2D50G6  | superseded by LC2D50AG7  |
| LC2D50G5  | superseded by LC2D50AG7  |
| LC2D50FE7 | superseded by LC2D50AFE7 |
| LC2D50FE5 | superseded by LC2D50AFE7 |
| LC2D50F7  | superseded by LC2D50AF7  |
| LC2D50F6  | superseded by LC2D50AF7  |
| LC2D50F5  | superseded by LC2D50AF7  |
| LC2D50E7  | superseded by LC2D50AE7  |
| LC2D50E6  | superseded by LC2D50AE7  |
| LC2D50E5  | superseded by LC2D50AE7  |
| LC2D50D7  | superseded by LC2D50AD7  |
| LC2D50B7  | superseded by LC2D50AB7  |
| LC2D50B6  | superseded by LC2D50AB7  |
| LC2D50B5  | superseded by LC2D50AB7  |
| LC2D40V7  | superseded by LC2D40AV7  |
| LC2D40V5  | superseded by LC2D40AV7  |
| LC2D40U7  | superseded by LC2D40AU7  |
| LC2D40U6  | superseded by LC2D40AU7  |
| LC2D40U5  | superseded by LC2D40AU7  |
| LC2D40T6  | superseded by LC2D40AT7  |
| LC2D40R7  | superseded by LC2D40AR7  |
| LC2D40R6  | superseded by LC2D40AR7  |
| LC2D40R5  | superseded by LC2D40AR7  |
| LC2D40Q7  | superseded by LC2D40AQ7  |
| LC2D40Q6  | superseded by LC2D40AQ7  |
| LC2D40Q5  | superseded by LC2D40AQ7  |
| LC2D40P7  | superseded by LC2D40AP7  |
| LC2D40P5  | superseded by LC2D40AP7  |
| LC2D40N7  | superseded by LC2D40AN7  |
| LC2D40N6  | superseded by LC2D40AN7  |
| LC2D40N5  | superseded by LC2D40AN7  |
| LC2D40M7  | superseded by LC2D40AM7  |
| LC2D40M6  | superseded by LC2D40AM7  |
| LC2D40M5  | superseded by LC2D40AM7  |
| LC2D40L7  | superseded by LC2D40AL7  |

|            |                           |
|------------|---------------------------|
| LC2D40K7   | superseded by LC2D40AK7   |
| LC2D40J5   | superseded by LC2D40AJ5   |
| LC2D40G7   | superseded by LC2D40AG7   |
| LC2D40G6   | superseded by LC2D40AG7   |
| LC2D40G5   | superseded by LC2D40AG7   |
| LC2D40FE7  | superseded by LC2D40AFE7  |
| LC2D40FE5  | superseded by LC2D40AFE7  |
| LC2D40F7   | superseded by LC2D40AF7   |
| LC2D40F6   | superseded by LC2D40AF7   |
| LC2D40F5   | superseded by LC2D40AF7   |
| LC2D40E7   | superseded by LC2D40AE7   |
| LC2D40E6   | superseded by LC2D40AE7   |
| LC2D40E5   | superseded by LC2D40AE7   |
| LC2D40D7   | superseded by LC2D40AD7   |
| LC2D40D5   | superseded by LC2D40AD7   |
| LC2D40B7   | superseded by LC2D40AB7   |
| LC2D40B6   | superseded by LC2D40AB7   |
| LC2D40B5   | superseded by LC2D40AB7   |
| LC1D65Y5   | superseded by LC1D65AYC7  |
| LC1D65V7   | superseded by LC1D65AV7   |
| LC1D65UD   | superseded by LC1D65AUD   |
| LC1D65U7TQ | superseded by LC1D65AU7TQ |
| LC1D65U7   | superseded by LC1D65AU7   |
| LC1D65U6   | superseded by LC1D65AU7   |
| LC1D65U5   | superseded by LC1D65AU7   |
| LC1D65SW   | superseded by LC1D65ASD   |
| LC1D65SD   | superseded by LC1D65ASD   |
| LC1D65S5   | superseded by LC1D65AS7   |
| LC1D65RD   | superseded by LC1D65ARD   |
| LC1D65R7   | superseded by LC1D65AR7   |
| LC1D65R6   | superseded by LC1D65AR7   |
| LC1D65Q7   | superseded by LC1D65AQ7   |
| LC1D65Q6   | superseded by LC1D65AQ7   |
| LC1D65P7   | superseded by LC1D65AP7   |
| LC1D65ND   | superseded by LC1D65AND   |
| LC1D65N7   | superseded by LC1D65AN7   |
| LC1D65N6   | superseded by LC1D65AN7   |
| LC1D65N5   | superseded by LC1D65AN7   |
| LC1D65MD   | superseded by LC1D65AMD   |
| LC1D65M7   | superseded by LC1D65AM7   |
| LC1D65LE7  | superseded by LC1D65ALE7  |
| LC1D65L6   | superseded by LC1D65ALE7  |
| LC1D65K7   | superseded by LC1D65AK7   |
| LC1D65JD   | superseded by LC1D65AJD   |
| LC1D65J5   | superseded by LC1D65AJ5   |
| LC1D65G6   | superseded by LC1D65AG7   |
| LC1D65FE7  | superseded by LC1D65AFE7  |
| LC1D65FE5  | superseded by LC1D65AFE7  |
| LC1D65FD   | superseded by LC1D65AFD   |
| LC1D65F7   | superseded by LC1D65AF7   |
| LC1D65F5   | superseded by LC1D65AF7   |
| LC1D65ED   | superseded by LC1D65AED   |

|              |                           |
|--------------|---------------------------|
| LC1D65E7     | superseded by LC1D65AE7   |
| LC1D65E5     | superseded by LC1D65AE7   |
| LC1D65D5     | superseded by LC1D65AD7   |
| LC1D65CW     | superseded by LC1D65ACD   |
| LC1D65C5     | superseded by LC1D65AC7   |
| LC1D65BD     | superseded by LC1D65ABD   |
| LC1D65B7     | superseded by LC1D65AB7   |
| LC1D65B5     | superseded by LC1D65AB7   |
| LC1D656SW    | superseded by LC1D65A6SD  |
| LC1D656R7    | superseded by LC1D65A6R7  |
| LC1D656Q7    | superseded by LC1D65A6Q7  |
| LC1D656P7    | superseded by LC1D65A6P7  |
| LC1D656P5    | superseded by LC1D65A6P7  |
| LC1D656M7    | superseded by LC1D65A6M7  |
| LC1D656M6    | superseded by LC1D65A6M7  |
| LC1D656M5    | superseded by LC1D65A6M7  |
| LC1D656LE7   | superseded by LC1D65A6LE7 |
| LC1D656L7    | superseded by LC1D65A6L7  |
| LC1D656K7    | superseded by LC1D65A6K7  |
| LC1D656GD    | superseded by LC1D65A6GD  |
| LC1D656G7    | superseded by LC1D65A6G7  |
| LC1D656G6    | superseded by LC1D65A6G7  |
| LC1D656FW    | superseded by LC1D65A6FD  |
| LC1D656FE7   | superseded by LC1D65A6FE7 |
| LC1D656FD    | superseded by LC1D65A6FD  |
| LC1D656F7    | superseded by LC1D65A6F7  |
| LC1D656ED    | superseded by LC1D65A6ED  |
| LC1D656E7    | superseded by LC1D65A6E7  |
| LC1D656BW    | superseded by LC1D65A6BD  |
| LC1D656BD    | superseded by LC1D65A6BD  |
| LC1D656B7    | superseded by LC1D65A6B7  |
| LC1D656B5    | superseded by LC1D65A6B7  |
| LC1D65004U7  | superseded by LC1DT80AU7  |
| LC1D65004U5  | superseded by LC1DT80AU7  |
| LC1D65004R5  | superseded by LC1DT80AR7  |
| LC1D65004P7  | superseded by LC1DT80AP7  |
| LC1D65004P5  | superseded by LC1DT80AP7  |
| LC1D65004N7  | superseded by LC1DT80AN7  |
| LC1D65004M7  | superseded by LC1DT80AM7  |
| LC1D65004FE7 | superseded by LC1DT80AFE7 |
| LC1D65004FE5 | superseded by LC1DT80AFE7 |
| LC1D65004F7  | superseded by LC1DT80AF7  |
| LC1D65004F5  | superseded by LC1DT80AF7  |
| LC1D65004E7  | superseded by LC1DT80AE7  |
| LC1D65004B7  | superseded by LC1DT80AB7  |
| LC1D65004B5  | superseded by LC1DT80AB7  |
| LC1D650046M7 | superseded by LC1DT80A6M7 |
| LC1D50Y5     | superseded by LC1D50AYC7  |
| LC1D50X6     | superseded by LC1D50AX7   |
| LC1D50W6     | superseded by LC1D50AW7   |
| LC1D50V7     | superseded by LC1D50AV7   |
| LC1D50U7     | superseded by LC1D50AU7   |

|           |                          |
|-----------|--------------------------|
| LC1D50U5  | superseded by LC1D50AU7  |
| LC1D50T6  | superseded by LC1D50AT7  |
| LC1D50SW  | superseded by LC1D50ASD  |
| LC1D50S6  | superseded by LC1D50ASC7 |
| LC1D50RD  | superseded by LC1D50ARD  |
| LC1D50R7  | superseded by LC1D50AR7  |
| LC1D50Q7  | superseded by LC1D50AQ7  |
| LC1D50Q6  | superseded by LC1D50AQ7  |
| LC1D50P7  | superseded by LC1D50AP7  |
| LC1D50P5  | superseded by LC1D50AP7  |
| LC1D50ND  | superseded by LC1D50AND  |
| LC1D50N7  | superseded by LC1D50AN7  |
| LC1D50N6  | superseded by LC1D50AN7  |
| LC1D50MD  | superseded by LC1D50AMD  |
| LC1D50M7  | superseded by LC1D50AM7  |
| LC1D50M5  | superseded by LC1D50AM7  |
| LC1D50LE7 | superseded by LC1D50ALE7 |
| LC1D50L7  | superseded by LC1D50AL7  |
| LC1D50K7  | superseded by LC1D50AK7  |
| LC1D50JW  | superseded by LC1D50AJD  |
| LC1D50JD  | superseded by LC1D50AJD  |
| LC1D50J5  | superseded by LC1D50AJ5  |
| LC1D50GD  | superseded by LC1D50AGD  |
| LC1D50G7  | superseded by LC1D50AG7  |
| LC1D50G5  | superseded by LC1D50AFC7 |
| LC1D50FW  | superseded by LC1D50AFD  |
| LC1D50FE7 | superseded by LC1D50AFE7 |
| LC1D50FE5 | superseded by LC1D50AFE7 |
| LC1D50FD  | superseded by LC1D50AFD  |
| LC1D50F7  | superseded by LC1D50AF7  |
| LC1D50F6  | superseded by LC1D50AF7  |
| LC1D50F5  | superseded by LC1D50AF7  |
| LC1D50ED  | superseded by LC1D50AED  |
| LC1D50E7  | superseded by LC1D50AE7  |
| LC1D50D7  | superseded by LC1D50AD7  |
| LC1D50D5  | superseded by LC1D50AD7  |
| LC1D50CW  | superseded by LC1D50ACD  |
| LC1D50BW  | superseded by LC1D50ABD  |
| LC1D50BD  | superseded by LC1D50ABD  |
| LC1D50B7  | superseded by LC1D50AB7  |
| LC1D50B5  | superseded by LC1D50AB7  |
| LC1D506U6 | superseded by LC1D50A6U7 |
| LC1D506SD | superseded by LC1D50A6SD |
| LC1D506R7 | superseded by LC1D50A6R7 |
| LC1D506Q7 | superseded by LC1D50A6Q7 |
| LC1D506P7 | superseded by LC1D50A6P7 |
| LC1D506P5 | superseded by LC1D50A6P7 |
| LC1D506M6 | superseded by LC1D50A6M7 |
| LC1D506L7 | superseded by LC1D50A6L7 |
| LC1D506JW | superseded by LC1D50A6JD |
| LC1D506GD | superseded by LC1D50A6GD |
| LC1D506G6 | superseded by LC1D50A6G7 |

|            |                           |
|------------|---------------------------|
| LC1D506G5  | superseded by LC1D50A6G7  |
| LC1D506FW  | superseded by LC1D50A6FD  |
| LC1D506FE7 | superseded by LC1D50A6FE7 |
| LC1D506FE5 | superseded by LC1D50A6FE7 |
| LC1D506FD  | superseded by LC1D50A6FD  |
| LC1D506F7  | superseded by LC1D50A6F7  |
| LC1D506EW  | superseded by LC1D50A6ED  |
| LC1D506ED  | superseded by LC1D50A6ED  |
| LC1D506E7  | superseded by LC1D50A6E7  |
| LC1D506D7  | superseded by LC1D50A6D7  |
| LC1D506CW  | superseded by LC1D50A6CD  |
| LC1D506CD  | superseded by LC1D50A6CD  |
| LC1D506BD  | superseded by LC1D50A6BD  |
| LC1D506B5  | superseded by LC1D50A6B7  |
| LC1D40W6   | superseded by LC1D40AW7   |
| LC1D40V7   | superseded by LC1D40AV7   |
| LC1D40V5   | superseded by LC1D40AV7   |
| LC1D40UD   | superseded by LC1D40AUD   |
| LC1D40U7   | superseded by LC1D40AU7   |
| LC1D40U5   | superseded by LC1D40AU7   |
| LC1D40T6   | superseded by LC1D40AT7   |
| LC1D40S6   | superseded by LC1D40AS7   |
| LC1D40R7   | superseded by LC1D40AR7   |
| LC1D40R5   | superseded by LC1D40AR7   |
| LC1D40Q7   | superseded by LC1D40AQ7   |
| LC1D40Q6   | superseded by LC1D40AQ7   |
| LC1D40P7   | superseded by LC1D40AP7   |
| LC1D40N7   | superseded by LC1D40AN7   |
| LC1D40N6   | superseded by LC1D40AN7   |
| LC1D40N5   | superseded by LC1D40AN7   |
| LC1D40MD   | superseded by LC1D40AMD   |
| LC1D40M7   | superseded by LC1D40AM7   |
| LC1D40LE7  | superseded by LC1D40ALE7  |
| LC1D40L7   | superseded by LC1D40AL7   |
| LC1D40K7   | superseded by LC1D40AK7   |
| LC1D40JD   | superseded by LC1D40AJD   |
| LC1D40G7   | superseded by LC1D40AG7   |
| LC1D40FE7  | superseded by LC1D40FE7   |
| LC1D40FE5  | superseded by LC1D40FE7   |
| LC1D40FD   | superseded by LC1D40AFD   |
| LC1D40F7   | superseded by LC1D40AF7   |
| LC1D40F6   | superseded by LC1D40AF7   |
| LC1D40F5   | superseded by LC1D40AF7   |
| LC1D40ED   | superseded by LC1D40AED   |
| LC1D40E7   | superseded by LC1D40AE7   |
| LC1D40E5   | superseded by LC1D40AE7   |
| LC1D40D7   | superseded by LC1D40AD7   |
| LC1D40C5   | superseded by LC1D40AC7   |
| LC1D40BW   | superseded by LC1D40ABD   |
| LC1D40BD   | superseded by LC1D40ABD   |
| LC1D40B7TQ | superseded by LC1D40AB7TQ |
| LC1D40B7   | superseded by LC1D40AB7   |

|              |                           |
|--------------|---------------------------|
| LC1D40B5     | superseded by LC1D40AB7   |
| LC1D406UD    | superseded by LC1D40A6UD  |
| LC1D406SW    | superseded by LC1D40A6SD  |
| LC1D406R7    | superseded by LC1D40A6R7  |
| LC1D406P7    | superseded by LC1D40A6P7  |
| LC1D406P5    | superseded by LC1D40A6P7  |
| LC1D406MW    | superseded by LC1D40A6MD  |
| LC1D406MD    | superseded by LC1D40A6MD  |
| LC1D406M7    | superseded by LC1D40A6M7  |
| LC1D406M6    | superseded by LC1D40A6M7  |
| LC1D406M5    | superseded by LC1D40A6M7  |
| LC1D406LE7   | superseded by LC1D40A6LE7 |
| LC1D406L7    | superseded by LC1D40A6L7  |
| LC1D406K7    | superseded by LC1D40A6K7  |
| LC1D406G7    | superseded by LC1D40A6G7  |
| LC1D406G6    | superseded by LC1D40A6G7  |
| LC1D406FW    | superseded by LC1D40A6FD  |
| LC1D406FE7   | superseded by LC1D40A6FE7 |
| LC1D406FD    | superseded by LC1D40A6FD  |
| LC1D406F7    | superseded by LC1D40A6F7  |
| LC1D406EW    | superseded by LC1D40A6ED  |
| LC1D406ED    | superseded by LC1D40A6ED  |
| LC1D406E7    | superseded by LC1D40A6E7  |
| LC1D406D5    | superseded by LC1D40A6D7  |
| LC1D406CW    | superseded by LC1D40A6CD  |
| LC1D406CD    | superseded by LC1D40A6CD  |
| LC1D406BW    | superseded by LC1D40A6BD  |
| LC1D406BD    | superseded by LC1D40A6B7  |
| LC1D406B7    | superseded by LC1D40A6B7  |
| LC1D406B5    | superseded by LC1D40A6B7  |
| LC1D40004U7  | superseded by LC1DT60AU7  |
| LC1D40004U5  | superseded by LC1DT60AU7  |
| LC1D40004P7  | superseded by LC1DT60AP7  |
| LC1D40004N7  | superseded by LC1DT60AN7  |
| LC1D40004N5  | superseded by LC1DT60AN7  |
| LC1D40004M7  | superseded by LC1DT60AM7  |
| LC1D40004M5  | superseded by LC1DT60AM7  |
| LC1D40004FE5 | superseded by LC1DT60AFE7 |
| LC1D40004F7  | superseded by LC1DT60AF7  |
| LC1D40004F5  | superseded by LC1DT60AF7  |
| LC1D40004E7  | superseded by LC1DT60AE7  |
| LC1D40004E5  | superseded by LC1DT60AE7  |
| LC1D40004B7  | superseded by LC1DT60AB7  |
| LC1D40004B5  | superseded by LC1DT60AB7  |
| LC1D400046P7 | superseded by LC1DT60A6P7 |
| LC1D400046M5 | superseded by LC1DT60A6M7 |
| LC1D400046E7 | superseded by LC1DT60A6E7 |
| LC1D400046B7 | superseded by LC1DT60A6B7 |
| GV3ME63      | superseded by GV3P50      |
| GV3ME63      | superseded by GV3P65      |
| GV3ME40      | superseded by GV3P32      |
| GV3ME40      | superseded by GV3P40      |

|         |                      |
|---------|----------------------|
| GV3ME25 | superseded by GV3P25 |
| GV3ME20 | superseded by GV3P13 |
| GV3ME20 | superseded by GV3P18 |
| GV3ME14 | superseded by GV2P14 |
| GV3ME10 | superseded by GV2P10 |
| GV3ME08 | superseded by GV2P08 |
| GV3ME07 | superseded by GV2P07 |
| GV3ME06 | superseded by GV2P06 |
| GK3EF65 | superseded by GV3L50 |
| GK3EF65 | superseded by GV3L65 |
| GK3EF40 | superseded by GV3L25 |
| GK3EF40 | superseded by GV3L32 |
| GK3EF40 | superseded by GV3L40 |