


415VAC 3 phase supply

Simple 240 VAC Control DOL Start Circuit
Using The Overload Stop Button


— = Control wiring



415VAC 3 phase supply

240 VAC Control DOL Start Circuit
Using Remote Stop Button


— = Control wiring



415VAC 3 phase supply

Simple 415VAC Control DOL Start Circuit
Using The Overload Stop Button

— = Control wiring



415VAC 3 phase supply

415 VAC Control DOL Start Circuit
Using Remote Stop Button

— = Control wiring

Contactor

Start

415VAC Coil

Remote Stop Button

A number of stop buttons, including
Emergency Stops*, can be wired in series
at this point

* Fitting of E Stops in this circuit may not be appropriate
depending on the requirements of the machine safety
risk assessment. If in doubt, refer to your safety consultant

3 Phase
Electric Motor

