

18 - December 2018

Release note of PMESWT 0100 Firmware V1.15

1/1

Date	PV	SV	Change description	Compatibility
18/12/2018	2	1.15	<p><u>New firmware version: PMESWT0100_1.15.Idx</u></p> <p><u>It includes</u></p> <ul style="list-style-type: none"> -SCAIME Weighing transmitter v1.00 IR 24 -M580 Partner Module Ethernet v2.10 IR 26 -PME ETH Core Bootloader v1.00 IR6 <p><u>Purpose of this new Firmware version</u></p> <ul style="list-style-type: none"> -Suppress the random freeze of applicative cyclic values, -Ruggedize the communication between the PMESWT0100 and the SWTOUCH HMI in case of disconnection & reconnection, -Hot Swap compliant in a HSBY system, -Fix a reset device issue from the DTM menu, -Ruggedize upgrade with unity loader, -Upgrade issue: Connection is lost after a firmware update via Unity Loader. -Fix a shift data with the DFB <p>This new firmware version must be installed with:</p> <ul style="list-style-type: none"> -Unity Pro v13.1 and -Unity Pro Hotfix V13.1_HF0470178R_DFB output pins" and -Unity Pro Hotfix V13.1_HF0465853R_SCAIME DTM" <p>Please follow the: PMESWT0100 Upgrade procedure</p>	<p>Unity loader V12.0 CPU 2.70 IR11 Standard / HSBY / Safety</p> <p>Unity Pro V13.1 and HotFix V131_HF0470178R HotFix V131_HF0465853R (PME DTM Lib 1.00.32) (PME Generic DTM 1.0.48)</p> <p>PMESWT_DFB_V4-49</p> <p>Download "Software and Upgrade procedures" on SCAIME Website: https://scaime.com/product/post/pmeswt See "FIRMWARE" or on Schneider-Electric Website https://www.schneider-electric.com/-/PME SWT0100 See "Documents and Downloads"</p>
12/01/2014	1	1.13	<p><u>Initial firmware version: PMESWT0100_1.13.Idx</u></p> <p><u>It includes</u></p> <ul style="list-style-type: none"> -SCAIME Weighing transmitter v1.00 IR 23 -M580 Partner Module Ethernet v1.00 IR 69 -PME ETH Core Bootloader v1.00 IR6 	<p>Unity Pro V11 or higher DTM 1.00.23 (PME Generic DTM 1.0.38)</p> <p>PMESWT_DFB_V4-47</p>

R001A07-B

227411-A-1/1