



Surge protection device (SPD)
Compliant with IEC 61643-11



PLEASE NOTE


- The installation, maintenance and eventual replacement of this device must only be carried out by a qualified electrician.
- This device must not be repaired.
- All applicable local, regional and national regulations must be complied with during the installation, use, maintenance and replacement of this device.
- This device should not be installed if, when unpacking it, you observe that it is damaged.
- Schneider Electric cannot be held responsible in the event of noncompliance with the instructions in this document and in the documents to which it refers.
- The service instruction must be observed throughout the life time of this device.

⚡ ⚠ DANGER



HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH

- Turn off all power supplying this product before working on it.
 - Use a voltage tester with a suitable rated voltage in order to check that all active conductors aren't energized.
 - Carefully inspect the work area to check that no tools or objects could have been left inside the equipment.
- Failure to follow these instructions will result in death or serious injury.

1 Description



2 Installation



14 mm	2.5...25 mm²	4...16 mm²
3.5 N.m	6.5 mm	PZ2

3

Installation verification test

NOTICE


HAZARD OF PRODUCT DAMAGE DURING INSULATION RESISTANCE TEST

The device must be disconnected before performing the insulation resistance test.

Failure to follow these instructions can result in equipment damage.


4

Cartridge replacement



5

More information



Schneider Electric Industries SAS

35, rue Joseph Monier

CS 30323

F - 92506 Rueil Malmaison Cedex

www.se.com

GEX2674901-00

© 2023 Schneider Electric - All rights reserved.

2/2