





Repulsion of the contacts, due to the energy delivered by the short-circuit



The energy due to the short-circuit becomes very high, the arc becomes important